

EXHIBIT 2

TECHNICAL ASSISTANCE CENTER

***** GM RESTRICTED *****

Case No:	06790339	VIN:	<input type="button" value="Privacy"/>
Date Opened:	20030918	Model Year:	2003
Date Closed:	05/12/2014	Model Series:	AJ
Dealer Code:	SI121918	Mileage:	009190
Dealer Name:	W. Gordon Walker South Holland	Dealer State:	IL
Dealer Phone:	7083316400	Division:	Saturn

SYMPTOM ABSTRACT--- STALL ENGINE ENGINE STALL INTERMITTENT

RESOLUTION ABSTRACT-

UCC CODE 1-----

UCC-1 DESCRIPTION— Engine

UCC CODE 2-----

UCC-2 DESCRIPTION—

UCC CODE 3-----

UCC-3 DESCRIPTION—

09/18/2003 15:21:35 SBD Template - VOELLINGER

tech stated ENGINE STALL INTERMITTENT.

tech cannot duplicate.

no codes.

**owner stated happened 6x. 1x on the highway and 5x at 20-25 mph while
cruising.**

owner stated the car restarts fine.

rec:

- uhjb 3 silver bolts.

- battery bolts

- battery state of charge.

- EI module connector for tt.

- check G301 and G101.

09/18/2003 15:21:35 History - VOELLINGER

09/19/2003 11:17:44 VOELLINGER - update-

tech checked the following and all ok:

- uhjb 3 silver bolts.

TECHNICAL ASSISTANCE CENTER

***** GM RESTRICTED *****

Case No:	06790339	VIN:	<input type="button" value="Privacy"/>
Date Opened:	20030918	Model Year:	2003
Date Closed:	05/12/2014	Model Series:	AJ
Dealer Code:	SI121918	Mileage:	009190
Dealer Name:	W. Gordon Walker South Holland	Dealer State:	IL
Dealer Phone:	7083316400	Division:	Saturn

- battery bolts
- battery state of charge.
- EI module connector for tt.
- check G301 and G101.

tech drove the car 52 miles and no duplication.

rec:

check the tt at the ignition switch.

find out if the owner has several keys on the chain.

if ok, release the car as unable to duplicate.